

# NORWOOD

NEVER ORDINARY

## Norcoat Flexacron Paint and Stain Finish

The Norcoat Flexacron coating is a premium quality, high performance finish and requires minimal maintenance.

Light accumulation of dirt can be removed using a garden hose equipped with a soft bristle brush. Heavier accumulations can be removed using a mild soap solution. For wet paint, tar and caulking use kerosene or mineral spirits. **DO NOT** use stronger solvents or abrasive type cleaners because they will damage the paint surface.

Mildew thrives on warmth and moisture that is most common near water such as the Great Lakes, the coast and other large bodies of water. If you live in an area of high humidity you should inspect your windows regularly for the presence of mildew and clean as needed, however, because mildew is so adaptable it can flourish in almost any climate.

Cracks resulting from joint movement should be caulked with high quality caulking materials such as Dow-734 silicone.

Minor nicks and scratches may be touched up with a matching Pittsburgh Paint 78-Line Sun-Proof semi-gloss acrylic latex paint.